Approved For Release 2003/04/29 CIA-RDH84-00780R001200040036-8

INTERNAL USE ONLY PAR Bldg 1 121/0

3 1 OCT 1966

MEMORANDUM FOR: Executive Officer to the Deputy Director for Support

SUBJECT : Light Switches in the Headquarters Building

- 1. This status report is in response to your request of 27 October 1966.
- 2. Subsequent to the date of our memorandum dated 12 September 1966, the following actions have been taken:
 - a. We have tested, satisfactorily, the plastic light switch covers under consideration.
 - b. The General Services Administration (GSA) has agreed to supply these switch covers, to paint them according to the standards of the Fine Arts Commission, and to install them, all at GSA expense.
 - c. Light switch covers have been ordered through GSA channels but have not yet been received.
- 3. We will continue to follow this matter closely and will advise you upon receipt of the light switch covers and prior to actual installation.

George E. Meloon Director of Logistics

Noted at DD/S Noon Meeting on 2 Nov 66.

Noted at DD/S Noon Meeting again on 18 Nov 66 ("visible progress")

Approved For Release 2003/04/29 : CIA-RDP84-00780R001200040036-8 15 September 1966

I called Jack Blake to run some expedite tests on the effectiveness of the switch plates if they are painted. The Fine Arts Commission suggested these switches be painted to match the walls and I was concerned whether this would reduce the effectiveness to arcing. Mr. Blake should have a report by the first part of next week.

R. L. Bannerman

STAT

- 9/13

MR. WARFIELD - 9/14

MR. BANNERMAN -

Approved For Release 2009/01/29 CIA RDP84-00780R001200040036-8 DD/S 66 -4/14/3 DD/S 66 -4/14/3

MEMORANDUM	FOR:	Deputy	Director	for	Support

SUBJECT : Light Switch Plates

STAT

STAT

1. This memorandum is for your information only.

2. This is a status report to you on what has happened affecting
the light switch plates since last I spoke with you on Tuesday, 6 September
1966. has shown the model plates to
Chairman of the Fine Arts Commission. has taken the
following position:

- His personal opinion is that they are acceptable if they are painted to match the walls to which they will be affixed.
- He does not wish to rule alone on this issue and, therefore, will submit his recommendation to the entire membership of the Fine Arts Commission during the week of 12 September 1966.

John F. Blake Deputy Director of Logistics

,	ROUTING AND R	ECORD	SHEET REGISTER
SUBJECT: (Optional)			SHEET DD/S REGISTRE FILE Blog + a/o
Switc	h Problem		FILEBUGS
FROM:		CIENSION	NO.
Director of Logistics			24 AUG 1966
TO: (Officer designotion, room number, on			TO LABORATE (I.I. I.I.
building)			COMMENTS (Number each comment to show from vito whom. Draw a line across calums ofter each comm
1.			
Executive Officer to the DD	26 AUG 1963		
7D18 Headquarters 2.			Attached is the latest informa-
-20	1 30 au.		tion on the lightswitch problem. Whave asked GSA to replace the Arr
Mr. Warfell	2 30 acg.		Hart switches and install the Bakel
3.			face plates. As a result of the me
Mr. Bannerman	4.2		ing described in the attached corre
4./			pondence, the representative of the
ha harlast	2 Loft.		GSA Protection Division believes the
5.			switches will not have to be replace if we cease using cleansing sprays
		•	He does support, as does the Arro
6.			Hart representative, installing the
0.			Bakelite face plates. We are now
			awaiting the final position of GSA a
7.			will keep you advised.
8.			G n
9. 10 1AA.	- MH		2-3: While I share your concern
1 mw 6 h	wat 4		that we really cannot tolerate
10.	man gra		another accident with light switches, I do believe that we
Tochnica M	plong me		would find it difficult to justify
III ranch. nz	Michiga		action which is not supported by
is show	· PIT O		the electricians. Perhaps one
Turn	0.		further cautionary letter to GSA
12. COVERNIE		į	would encourage them to take
	166		one more look at the problem.
13.	2 40/		Neither they nor the manufacture will ever issue a guarantee no
•			matter how much we would like
14.		!	them to.
and the same of th			
15.			
			Alan M. Waxfield

ORAFT/DMK:mew 0/22/66

STAT

STAT

MEMORANDUM FOR: Deputy Director of Logistics

SUBJECT

: Switch Problem

1. In accordance with your request we have attached a memo for the record obtained from _______ which reflects the result of the recent meeting on 10 August 1966 with the switch manufacturer. _______ is presently awaiting instructions from the Central Office to replace the system.

2. You will note on Page 2 of the attached memo for record that two recommendations have been made. First, that the use of spray cleaner on light switches be discontinued permanently, and secondly, all aluminum and stainless steel face plates should be replaced by Bakelite faced plates which gives an additional margin of safety.

A Chief, Logistics Services Division, Ol

Att